



Hygrometer Readings Report

To print the Hygrometer Readings Report, navigate to the job using your preferred search method. From the job single click on the **Moisture Readings** tab → click the **Printer** icon to generate the Report.

Job Name: Texturing -
PO#1225968

Job #: 19-103H20

Job Progress **Customer**
Contacted

Loss Type: Water Damage



Shiloh Condo - CC#1321654, Property (904) 222-5544 - Cell
Joe Smith, Owner 904-222-5555 - Cell
124 9th 1st Street, Unit 125, Jax Beach, FL 32250

Tasks: 0 Incomplete: 0 Due Today: 0 Overdue: 0 Future: 0
Documents: 2
Correspondence: 3
WOs: 0 Open: 0 Due Today: 0 Overdue: 0 Review: 0 Repair: 0
Equipment: Out: 1 Returned: 0 Total: 1

Referred By Previous Customer
Source of Referral Previous Customer (Other Referral Sources)
TPA Alacrity - Complex (Alacrity)
Property Manager Michael Jasper (**Jacksonville Property Mgmt)

Job Snapshot

- Detail
- Job Contacts (2)
- Additional Contacts (3)
- Losses (1)
- Schedules
- Tasks
- Subs/Techs
- Financials
- Correspondence (3)
- Documents & Pics (2)
- Document Merge
- Inspections
- Moisture Readings (1)
- Equipment**
- Change Log

General

Employee

- Detail
- Job Contacts (2)
- Additional Contacts (3)
- Losses (1)
- Schedules
- Tasks
- Subs/Techs
- Financials
- Correspondence (3)
- Documents & Pics (2)
- Document Merge
- Inspections
- Moisture Readings (1)
- Equipment**
- Change Log

- Loss Classification

Water Category:

Water Class:



- Unaffected Area

Temp

RH

GPP

Outside:



Inside:



Inside Area:

+ Unaffected Readings History

- Affected Areas

Affected Areas:



Print



Hygrometer Readings Report

Report Options: Print, Save as a PDF, Email, or Open in New Tab.

Hygrometer Readings Report:

RM Restoration
7991 Shaffer Parkway, Suite 300
Jax Beach, FL 32250
Office: (303) 800-5182 | Fax: (866) 413-0928

Hygrometer Readings

02/21/2019

Job #:	19-103H20	Claim #:	
Company:	*Jacksonville Property Mgmt		
Loss Address:	124 9th 1st Street, Unit 125, Jax Beach, FL 32250		
Job Contact	Shiloh Condo - CC#1321654		
Job Contact	Joe Smith		
Loss Type:	Water Damage		
Project Mgr:	Project Manager	Estimator:	Dawn Bryant

Water Category: Cat 2 - Gray Water **Class:** Class 2

Unaffected Area Readings

<u>Date</u>	<u>Employee</u>	<u>Area</u>	<u>Temp</u>	<u>RH %</u>	<u>GPP</u>
02/21/2019 04:37 PM	Dawn Bryant	Outside	78.0	54	78.42
02/21/2019 04:37 PM	Dawn Bryant	Inside: Bath - Hall	73.0	45	54.96

Laundry Room

Hygrometer

<u>Date</u>	<u>Employee</u>	<u>Area / Equipment</u>	<u>Temp</u>	<u>RH %</u>	<u>GPP</u>
02/21/2019 04:41 PM	Dawn Bryant	Laundry Room	71.0	89	102.66
02/21/2019 04:41 PM	Dawn Bryant	CF 123	105.0	15	50.88

Moisture Content

<u>Date</u>	<u>Employee</u>	<u>Wall</u>	<u>Door?</u>	<u>Material</u>	<u>MC %</u>	<u>Goal</u>
02/21/2019 04:41 PM	Dawn Bryant	Wall1	Yes	Drywall	40	10
02/21/2019 04:41 PM	Dawn Bryant	Wall2	No	Drywall	25	10
02/21/2019 04:41 PM	Dawn Bryant	Wall3	No	Drywall	10	10
02/21/2019 04:41 PM	Dawn Bryant	Wall4	No	Drywall	10	10
02/21/2019 04:41 PM	Dawn Bryant	Ceiling	-	Drywall	47	10
02/21/2019 04:41 PM	Dawn Bryant	Floor	-	Hardwood	35	10

Equipment

<u>Name</u>	<u>Class</u>	<u>Start</u>	<u>End</u>
CF 123	Air Mover	02/21/2019 04:38 PM	